

# The USFT PT-V3

At US Fleet Tracking, customer service is our top priority. If you have any questions or encounter any difficulties with this system, please contact our technical support at (405) 726-9900. Technicians are available Monday through Friday 7 a.m. to 7 p.m. CT and Saturday 9 a.m. to 4 p.m. CT.

If you have any questions about the web interface, control panel, or basics of GPS tracking and our system, please contact us so that we can help you succeed and get the most from our live GPS tracking system. Our staff will help you understand the ins and outs of GPS trackers and the US Fleet Tracking web interface with the many features it has to offer.

Thank you for choosing the PT-V3 personal tracking device from US Fleet Tracking.



# PT-V3

Live Tracking Device  
Better Connectivity



Thank you for choosing the PT-V3 personal GPS tracking device!

The PT-V3 is as simple as it gets. There are no buttons, no controls, no complications. Simply charge the device using the included AC adapter. Once charged, clip it onto your belt. If placing the PT-V3 in a case, please make sure the smooth side (opposite the belt clip) is facing up towards the top of the case (opposite the magnet).

If moving less than 10mph, the device will transmit every 20 feet. If moving faster than 10mph, the device will transmit every 10 seconds.

After installation, log onto your account at [www.usfleettracking.com](http://www.usfleettracking.com) using your user ID and password. From there you will have a complete view of your GPS tracker and its information.

If you find that your device is not performing as it should, there are three common issues.

## Poor satellite visibility

The GPS antenna cannot see through metal. Changing the location of the device to give it a better view of the sky should resolve the problem.

## Device has no power

Check to confirm the lights blink periodically on the top of the device. Recharge the battery to continue operation.

## No wireless data service

It's possible you could be in an area with poor or limited GSM wireless data service. Consult GSM coverage maps to confirm, or move the device to a more populated area to see if the problem persists.



PT-V3 Antenna